

SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	POINT-OF-ENTRY OR POINT-OF-USE TREATMENT PRESENT?	BUILDING PLUMBING MATERIAL 1	BUILDING PLUMBING MATERIAL 2	BUILDING PLUMBING MATERIAL INSTALL DATE	COMMENTS	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	WAS STREET SIDE MATERIAL FIELD VERIFIED?	DATE OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF STREET SIDE FIELD VERIFICATION, IF APPLICABLE	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
	100 HILL ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2017	Visual Insp at meter	Street Side: No records (may contain lead);
	100 RIVER ST	UNK	UNK-LG	UNK			UNK-LG			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	100 W 3RD ST	N	UNK-NoL	UNK	2"	1994	UNK-NoL			NONRES						SL repair/replace record	N			Other - describe in notes	N			Property Side: Aerial photography shows development after lead ban;
	1000 FARHAM DR	UNK	UNK-LG	UNK			UNK-LG			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	1001 S MAIN ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2014	Visual Insp at meter	Street Side: No records (may contain lead);
	1002 S MAIN ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2022	Visual Insp at meter	Street Side: No records (may contain lead);
	1005 S MAIN ST	N	UNK-NoL	UNK		2000	C			SF						Installed after lead ban	N			Field inspection only	Y	2014	Visual Insp at meter	Street Side: No records (may contain lead);
	1008 S MAIN ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2012	Visual Insp at meter	Street Side: No records (may contain lead);
	101 CENTER ST	UNK	UNK-LG	UNK			UNK-LG			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	101 DIVISION ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	Street Side: No records (may contain lead);
	101 OAK ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	Street Side: No records (may contain lead);
	101 S MAIN ST	UNK	UNK-LG	UNK			UNK-NoL			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	101 S SHERIDAN ST	UNK	UNK-LG	UNK			UNK-LG			MF						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	1011 S MAIN ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2015	Visual Insp at meter	Street Side: No records (may contain lead);
	102 W 8TH ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	Street Side: No records (may contain lead);
	103 DIVISION ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2013	Visual Insp at meter	Street Side: No records (may contain lead);
	103 OAK ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2017	Visual Insp at meter	Street Side: No records (may contain lead);
	103 PLUM ST	UNK	UNK-LG	UNK			UNK-LG			SF						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	103 W 6TH ST	N	P	UNK	1"	2018	G			SF						SL repair/replace record	N			Field inspection only	Y	2020	Visual Insp at meter	
	104 E 4TH ST	UNK	UNK-LG	UNK			G			SF						Other - describe in notes	N			Field inspection only	Y	2013	Visual Insp at meter	Street Side: No records (may contain lead);
	104 HARVEY ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	Street Side: No records (may contain lead);
	105 HARVEY ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2013	Visual Insp at meter	Street Side: No records (may contain lead);
	105 OAK ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	Street Side: No records (may contain lead);
	105 S PLUM ST	UNK	UNK-LG	UNK			UNK-NoL			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	107 DIVISION ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2013	Visual Insp at meter	Street Side: No records (may contain lead);
	107 OAK ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2017	Visual Insp at meter	Street Side: No records (may contain lead);
	107 S MAIN ST	UNK	UNK-LG	UNK			C			NONRES						Other - describe in notes	N			Field inspection only	Y	2012	Visual Insp at meter	Street Side: No records (may contain lead);
	109 DIVISION ST	N	UNK-LG	UNK			C			SF						SL repair/replace record	N			Field inspection only	Y	2012	Visual Insp at meter	Street Side: No records (may contain lead);
	1101 WEST ST	N	C	UNK	1"	1993	P			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	
	1102 WEST ST	N	C	UNK	1"	1993	C			SF						SL repair/replace record	N			Field inspection only	Y	2018	Visual Insp at meter	
	1103 S MAIN ST	N	UNK-NoL	UNK		2000	C			SF						Installed after lead ban	N			Field inspection only	Y	2018	Visual Insp at meter	
Lot 1	1103 WEST ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	Street Side: No records (may contain lead);
Lot 2	1109 WEST ST	N	C	UNK	1"	1993	DNE			NONRES						SL repair/replace record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	1104 WEST ST	N	C	UNK	1"	1993	C			SF						SL repair/replace record	N			Field inspection only	Y	2015	Visual Insp at meter	
	1105 WEST ST	N	C	UNK	1"	1993	C			SF						SL repair/replace record	N			Field inspection only	Y	2012	Visual Insp at meter	
	1106 BLUFF ST	UNK	UNK-LG	UNK			C			MF						Other - describe in notes	N			Field inspection only	Y	2014	Visual Insp at meter	Street Side: No records (may contain lead);
1110 Bluff St	1106 BLUFF ST	UNK	UNK-LG	UNK			C			MF						Other - describe in notes	N			Field inspection only	Y	2014	Visual Insp at meter	Street Side: No records (may contain lead);
102 12th St	1106 BLUFF ST	UNK	UNK-LG	UNK			UNK-LG			SF						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	1106 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	1106 WEST ST	UNK	UNK-LG	UNK			UNK-LG			SF						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	1107 S MAIN ST	N	UNK-NoL	UNK		2000	C			SF						Installed after lead ban	N			Field inspection only	Y	2016	Visual Insp at meter	Street Side: No records (may contain lead);
	111 OAK ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2018	Visual Insp at meter	Street Side: No records (may contain lead);
	111 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	1111 S MAIN ST	UNK	UNK-LG	UNK			P			NONRES						Other - describe in notes	N			Field inspection only	Y	2013	Visual Insp at meter	Street Side: No records (may contain lead);
11th St Lot 1	111h St Lot 1	N	C	UNK	1"	1993	DNE			NONRES						SL repair/replace record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
1201 Precision Parkway	1201 Precision Parkway	UNK	UNK-LG	UNK			C			NONRES						Other - describe in notes	N			Field inspection only	Y	2011	Visual Insp at meter	Street Side: No records (may contain lead);
1202 Weston St	1202 Weston St	N	C	UNK	1"	1993	UNK-NoL			SF						SL repair/replace record	N			Other - describe in notes	N			Property Side: Aerial photography shows development after lead ban;
	1203 WEST ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2016	Visual Insp at meter	Street Side: No records (may contain lead);
Building 3	1205 S MAIN ST	N	C	UNK	1"	1993	UNK-LG			SF						SL repair/replace record	N			Other - describe in notes	N			Property Side: No records (may contain lead);
Building 4	1205 S MAIN ST	N	C	UNK	1"	1993	UNK-LG			SF						SL repair/replace record	N			Other - describe in notes	N			Property Side: No records (may contain lead);
Building 2	1205 S MAIN ST	N	C	UNK	1"	1993	UNK-LG			SF						SL repair/replace record	N			Other - describe in notes	N			Property Side: No records (may contain lead);
Building 1	1205 S MAIN ST	N	C	UNK	1"	1993	UNK-LG			SF						SL repair/replace record	N			Other - describe in notes	N			Property Side: No records (may contain lead);
Building 5	1205 S MAIN ST	N	C	UNK	1"	1993	UNK-LG			SF						SL repair/replace record	N			Other - describe in notes	N			Property Side: No records (may contain lead);
Empty lot west of bldgs at 1205 12TH ST	1205 S MAIN ST	N	C	UNK	1"	1993	DNE			NONRES						Installation record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Building 6	1205 S MAIN ST	N	C	UNK	1"	1993	UNK-LG			SF						SL repair/replace record	N			Other - describe in notes	N			Property Side: No records (may contain lead);
	1206 WEST ST	UNK	UNK-LG	UNK			P			SF						Other - describe in notes	N			Field inspection only	Y	2012	Visual Insp at meter	Street Side: No records (may contain lead);
	1207 S MAIN ST	N	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2023	Visual Insp at meter	Street Side: No records (may contain lead);
	1207 WEST ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2014	Visual Insp at meter	Street Side: No records (may contain lead);
12th St Lot 1	12th St Lot 1	N	C	UNK	1"	1993	DNE			NONRES						SL repair/replace record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
12th St Lot 2	12th St Lot 2	N	C	UNK	1"	1993	DNE			NONRES						SL repair/replace record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
12th St Lot 3	12th St Lot 3	N	C	UNK	1"	1993	DNE			NONRES						SL repair/replace record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	1300 PRECISION PKWY	N	C	UNK	1"	1993	DNE			NONRES						SL repair/replace record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	1301 PRECISION PKWY	UNK	UNK-LG	UNK			C			NONRES						Other - describe in notes	N			Field inspection only	Y	2023	Visual Insp at meter	Street Side: No records (may contain lead);
	1301 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead);
	1309 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG			NONRES						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	1305 S MAIN ST	UNK	UNK-LG	UNK			C			MF						Other - describe in notes	N			Field inspection only	Y	2022	Visual Insp at meter	Street Side: No records (may contain lead);
1307 S Main St	1305 S MAIN ST	UNK	UNK-LG	UNK			UNK-NoL			MF						Other - describe in notes	N			Other - describe in notes	N			Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
100 Kudrek St. Apt. #13-16	1305 S MAIN ST	N	C	UNK	1 1/2"	1994	C			MF						SL repair/replace record	N			Field inspection only	Y	2015	Visual Insp at meter	
	1320 MAIN ST	UNK	UNK-LG	UNK			C			SF						Other - describe in notes	N			Field inspection only	Y	2014	Visual Insp at meter	Street Side: No records (may contain lead);
	1407 WHEELHAN AVE	N	C	N	1"	1994	UNK-NoL			MF						Installation record	N			Other - describe in notes	N			Property Side: Aerial photography shows development after lead ban;
Wheelhan Ave Lot 17	1408 WHEELHAN AVE	N	C	N	1 1/2"	1994	DNE			NONRES						Installation record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Wheelhan Ave Lot 16	1408 WHEELHAN AVE	N	C	N	1 1/2"	1994	DNE			NONRES						Installation record	N			Other - describe in notes	N			Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	1408 WHEELHAN AVE	N	C	N	1"	1994	UNK-NoL			NONRES						Installation record	N			Other - describe in notes	N			Street developed in 1994, lot developed after 1994.
	1412 WHEELHAN AVE	N	C	N	1 1/2"	1994	UNK-NoL			NONRES						Installation record	N			Other - describe in notes	N			Property Side: Aerial photography shows development after lead ban;
	1509 WHEELHAN AVE	N	C	N	1"	1994	UNK-NoL			SF						Installation record	N			Other - describe in notes	N		</	

Bluff St Lot 186	204 W 7TH ST APT 111	N	UNK-NoL	N	1"	2000	UNK-NoL	SF	Installed after lead ban	N	Other - describe in notes	N	Property Side: Aerial photography shows development after lead ban;
	204 W 7TH ST APT 111	N	UNK-NoL	N	1"	2000	UNK-NoL	SF	Installed after lead ban	N	Other - describe in notes	N	Property Side: Aerial photography shows development after lead ban;
	204 W 7TH ST APT 111	N	UNK-NoL	N	1"	1994	UNK-NoL	SF	Installation record	N	Field inspection only	Y	2017 Visual Insp at meter
	205 CARDINAL DR	N	C	N	1"	1994	C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter
	205 DIVISION ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter
	205 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
	205 JOHN ST	UNK	UNK-LG	UNK			UNK-LG	SF	SL repair/replace record	N	Other - describe in notes	N	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	205 N MAIN ST	UNK	C	UNK	1"	1982	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	205 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	205 W 12TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter
	206 DIVISION ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter
	206 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter
	206 JOHN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter
West St Lot 179	206 W 7TH ST	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter
West St Lot 180	206 W 7TH ST	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
West St Lot 182	206 W 7TH ST	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
West St Lot 183	206 W 7TH ST	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
West St Lot 181	206 W 7TH ST	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
West St Lot 178	206 W 7TH ST	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	207 CARDINAL DR	N	C	N	1"	1994	P	SF	Installation record	N	Field inspection only	Y	2011 Visual Insp at meter
	207 DIVISION ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter
	207 N MAIN ST	UNK	C	UNK	1"	1982	C	SF	SL repair/replace record	N	Field inspection only	Y	2024 Visual Insp at meter
	207 PLUM ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter
	208 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2019 Visual Insp at meter
	209 DIVISION ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter
	209 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	209 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
	209 W 3RD ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2011 Visual Insp at meter
	211 PLUM ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	211 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	211 W 3RD ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2020 Visual Insp at meter
	212 CENTER ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter
	212 S MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter
	212 W 3RD ST	UNK	UNK-LG	UNK			CL	NONRES	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter
	213 S MAIN ST	UNK	UNK-LG	UNK			P	NONRES	Other - describe in notes	N	Field inspection only	Y	2023 Visual Insp at meter
	214 PLUM ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	215 S MAIN ST	UNK	UNK-LG	UNK			P	NONRES	Other - describe in notes	N	Field inspection only	Y	2023 Visual Insp at meter
	217 CENTER ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2024 Visual Insp at meter
	217 Lakeview Ct, Lakeview Ct Lot 66	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 67	N	UNK-NoL	N	1"	2000	C	NONRES	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter	
217 Oak Grove Dr, Lakeview Ct Lot 68	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;	
217 Oak Grove Dr, Lakeview Ct Lot 69	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;	
217 Oak Grove Dr, Lakeview Ct Lot 70	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;	
	217 S MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter
	220 S MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter
	221 S MAIN ST B	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter
	223 CENTER ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2023 Visual Insp at meter
	227 S MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2019 Visual Insp at meter
	228 OAK GROVE DR	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Field inspection only	Y	2019 Visual Insp at meter
	228 OAK GROVE DR	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	228 OAK GROVE DR	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	228 OAK GROVE DR	N	UNK-NoL	N	1"	2000	DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	228 OAK GROVE DR	N	UNK-NoL	N	1"	2000	P	SF	Other - describe in notes	N	Field inspection only	Y	2022 Visual Insp at meter
	229 S MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter
	230 S MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2020 Visual Insp at meter
	231 S MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter
	245 OAK GROVE DR	N	UNK-NoL	N	1"	2000	C	SF	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter
	247 OAK GROVE DR	N	UNK-NoL	N	1"	2000	C	SF	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter
	300 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	300 W 13TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter
	300 W 13TH ST	N	C	UNK	1"	2018	UNK-LG	SF	SL repair/replace record	N	Other - describe in notes	N	Property Side: No records (may contain lead);
	301 CARDINAL DR	N	C	N	1"	1994	C	SF	Installation record	N	Field inspection only	Y	2012 Visual Insp at meter
	301 DIVISION ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter
301 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2021 Visual Insp at meter	
301 PLUM ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	
301 W 12TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	
302 CARDINAL DR	N	C	N	1"	1994	UNK-NoL	SF	Installation record	N	Other - describe in notes	N	Street developed in 1994, lot developed after 1994.	
303 CARDINAL DR	N	C	N	1"	1994	C	SF	Installation record	N	Field inspection only	Y	2012 Visual Insp at meter	
303 W 12TH ST	N	C	UNK	1"	1993	C	SF	SL repair/replace record	N	Field inspection only	Y	2018 Visual Insp at meter	
	303 W 6TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
	303 W 9TH ST	N	C	UNK	1"	1993	DNE	NONRES	SL repair/replace record	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	303 W 9TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2020 Visual Insp at meter
	303 W 9TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2020 Visual Insp at meter
	303 W 9TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2024 Visual Insp at meter
	303 W 9TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
	303 W 9TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
	303 W 9TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
	303 W 9TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
	303 W 9TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);
303 W 9TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Street Side: No records (may contain lead); Property Side: Aerial photography shows vacant lot;	
303 W 9TH ST	UNK	UNK-LG	UNK			DNE	SF	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Street Side: No records (may contain lead);	
303 W 9TH ST	UNK	UNK-LG	UNK			DNE	SF	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Street Side: No records (may contain lead);	
303 W 9TH ST	UNK	UNK-LG	UNK			DNE	SF	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Street Side: No records (may contain lead);	
303 W 9TH ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	
303 W 9TH ST	UNK	UNK-LG	UNK			DNE	SF	Other - describe in notes	N	Other - describe in notes	N	Property side service line does not exist. Street Side: No records (may contain lead);	
303 W 9TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2024 Visual Insp at meter	
304 HARVEY ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);	
304 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	
304 W 12TH ST	N	C	UNK	1"	1993	UNK-LG	SF	SL repair/replace record	N	Other - describe in notes	N	Property Side: No records (may contain lead);	
304 W 2ND ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	
304 W 9TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2023 Visual Insp at meter	
305 PLUM ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	
305 W 13TH ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);	
306 CARDINAL DR	N	C	N	1"	1994	P	SF	Installation record	N	Field inspection only	Y	2012 Visual Insp at meter	
308 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	
308 JOHN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	
306 W 9TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter	
307 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	
307 JOHN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	
307 PLUM ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	
307 W 13TH ST	UNK	UNK-LG	UNK			UNK-NoL	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);	
308 JOHN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	
308 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	
309 CARDINAL DR	N	C	N	1"	1994	DNE	NONRES	Installation record	N	Other - describe in notes	N	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;	
309 CARDINAL DR	N	C	N	1"	1994	UNK-NoL	SF	Installation record	N	Other - describe in notes	N	Street developed in 1994, lot developed after 1994.	
309 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2021 Visual Insp at meter	
309 W 13TH ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	
310 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N	Street Side: No records (may contain lead);	
311 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	
312 KUCIREK ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2024 Visual Insp at meter	
313 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	
314 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	
316 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	
400 BIRCH ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter	
400 S MAIN ST	UNK	UNK-LG	UNK			P	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	
400 W 2ND ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	
400 W 5TH ST	N	C	UNK	1"	2018	C	SF	SL repair/replace record	N	Field inspection only	Y	2018 Visual Insp at meter	
401 DIVISION ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	
401 JOHN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field inspection only	Y	2023 Visual Insp at meter	
401 N MAIN ST	UNK	UNK-LG											

	401 W 6TH ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	402 N MAIN ST	UNK	UNK-LG	UNK	UNK-NoL	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	402 PEACH ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	402 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	403 DIVISION ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	403 HARVEY ST	UNK	UNK-LG	UNK	UNK-LG	MF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	403 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	404 W 5TH ST	N	P	UNK	UNK-LG	SF	SL repair/replace record	N	Other - describe in notes	N		Property Side: No records (may contain lead);
	405 HARVEY ST	UNK	UNK-LG	UNK	1"	2018 UNK-LG	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	407 JOHN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2020 Visual Insp at meter	Street Side: No records (may contain lead);
	407 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	407 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	Street Side: No records (may contain lead);
	408 N MAIN ST	N	UNK-NoL	UNK	1994 C	MF	SL repair/replace record	N	Field inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead);
	410 S MAIN ST	UNK	UNK-LG	UNK	C	MF	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead);
	411 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	412 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	490 W 9TH ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	500 MAPLE ST	UNK	UNK-LG	UNK	C	UNK	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	501 BLUFF ST	UNK	UNK-LG	UNK	C	NONRES	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	501 JOHN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	501 N MAIN ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead);
	501 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	501 WESTON ST	N	P	UNK	2018 C	SF	Installation record	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	502 1ST ST W	UNK	UNK-LG	UNK	UNK-NoL	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	502 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	502 JOHN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	502 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	503 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	503 JOHN ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	503 MAPLE ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	503 PEACH ST	N	UNK-NoL	UNK	2000 C	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	503 W 6TH ST	N	UNK-LG	UNK	C	SF	SL repair/replace record	N	Field inspection only	Y	2023 Visual Insp at meter	Street Side: No records (may contain lead);
	504 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	504 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	505 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	505 JOHN ST	UNK	UNK-LG	UNK	P	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	505 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	505 W 1ST ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2023 Visual Insp at meter	Street Side: No records (may contain lead);
	505 W 6TH ST	N	UNK-NoL	UNK	2000 C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	505 WESTON ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	506 BLUFF ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2025 Visual Insp at meter	Street Side: No records (may contain lead);
	506 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	507 JOHN ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead);
	507 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	507 PEACH ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	508 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2024 Visual Insp at meter	Street Side: No records (may contain lead);
	508 JOHN ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	509 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2011 Visual Insp at meter	Street Side: No records (may contain lead);
	509 JOHN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	509 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2019 Visual Insp at meter	Street Side: No records (may contain lead);
	509 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	510 BLUFF ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	511 S MAIN ST	N	P	UNK	1"	2018 C	SL repair/replace record	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	511 WESTON ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Oak Grove Dr Lot 7	515 OAK GROVE DR	N	UNK-NoL	N	1"	2000 DNE	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Oak Grove Dr Lot 9	515 OAK GROVE DR	N	UNK-NoL	N	1"	2000 DNE	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Oak Grove Dr Lot 6	515 OAK GROVE DR	N	UNK-NoL	N	1"	2000 DNE	Installed after lead ban	N	Other - describe in notes	N		Property Side: Aerial photography shows development after lead ban;
Oak Grove Dr Lot 8	515 OAK GROVE DR	N	UNK-NoL	N	1"	2000 UNK-NoL	Installed after lead ban	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	555 KUCIREK ST	UNK	UNK-LG	UNK	UNK-NoL	NONRES	Other - describe in notes	N	Field inspection only	Y	2019 Visual Insp at meter	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 100	600 LAKEVIEW CT	N	UNK-NoL	N	1"	2000 P	Installed after lead ban	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
Lakeview Ct Lot 99	600 LAKEVIEW CT	N	UNK-NoL	N	1"	2000 DNE	Installed after lead ban	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	600 S MAIN ST	UNK	UNK-LG	UNK	UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead);
	600 WINKER ST	UNK	UNK-LG	UNK	UNK-NoL	SF	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	601 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	601 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	601 PRECISION PKWY	UNK	UNK-LG	UNK	UNK-LG	SF	SL repair/replace record	N	Field inspection only	Y	2011 Visual Insp at meter	Street Side: No records (may contain lead);
	601 W 3RD ST	N	UNK-NoL	UNK	2012 C	NONRES	Installed after lead ban	N	Field inspection only	Y	2019 Visual Insp at meter	Street Side: No records (may contain lead);
Lakeview Ct Lot 98	602 LAKEVIEW CT	N	UNK-NoL	UNK	1"	2000 P	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 97	602 LAKEVIEW CT	N	UNK-NoL	UNK	1"	2000 DNE	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	602 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	602 W 1ST ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	602 W 3RD ST	UNK	UNK-LG	UNK	C	NONRES	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	602 WINKER ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	603 HARVEY ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Field inspection only	Y	2024 Visual Insp at meter	Street Side: No records (may contain lead);
	603 JOHN ST	UNK	UNK-LG	UNK	C	NONRES	Other - describe in notes	N	Field inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	603 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	603 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	603 W 2ND ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	603 W 3RD ST	UNK	UNK-LG	UNK	UNK-NoL	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	603 W NORTH ST	UNK	UNK-LG	UNK	UNK-NoL	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
Lot 2	603 WEST ST	N	UNK-NoL	UNK	1 1/2"	2000 DNE	Installed after lead ban	N	Field inspection only	Y	2016 Visual Insp at meter	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lot 1	603 WEST ST	N	UNK-NoL	UNK	1 1/2"	2000 C	Installed after lead ban	N	Other - describe in notes	N		Property Side: Aerial photography shows development after lead ban;
Lakeview Ct Lot 96	604 LAKEVIEW CT	N	UNK-NoL	N	1"	2000 UNK-NoL	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 95	604 LAKEVIEW CT	N	UNK-NoL	N	1"	2000 DNE	Installation record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Vacant lot east of 604 N MAIN ST	604 N MAIN ST	N	UNK-NoL	UNK	1994 DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead);
	604 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2023 Visual Insp at meter	Street Side: No records (may contain lead);
	604 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	Street Side: No records (may contain lead);
	604 W 2ND ST	UNK	UNK-LG	UNK	C	MF	Other - describe in notes	N	Field inspection only	Y	2021 Visual Insp at meter	Street Side: No records (may contain lead);
	605 HARVEY ST	UNK	UNK-LG	UNK	C	NONRES	Other - describe in notes	N	Field inspection only	Y	2020 Visual Insp at meter	Street Side: No records (may contain lead);
	605 JOHN ST	UNK	UNK-LG	UNK	C	NONRES	Other - describe in notes	N	Field inspection only	Y	2022 Visual Insp at meter	Street Side: No records (may contain lead);
	605 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	605 PRECISION PKWY	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	605 WEST ST	N	UNK-NoL	UNK	1 1/2"	2000 UNK-LG	Installed after lead ban	N	Other - describe in notes	N		Property Side: No records (may contain lead);
	606 BLUFF ST	N	P	UNK	1"	2018 UNK-LG	SL repair/replace record	N	Field inspection only	Y	2021 Visual Insp at meter	Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 94	606 LAKEVIEW CT	N	UNK-NoL	N	1"	2000 C	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 93	606 LAKEVIEW CT	N	UNK-NoL	N	1"	2000 DNE	Installed after lead ban	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	606 PRECISION PKWY	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	Street Side: No records (may contain lead);
	606 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	607 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2015 Visual Insp at meter	Street Side: No records (may contain lead);
	607 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	607 WESTON ST	UNK	UNK-LG	UNK	UNK-LG	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	608 BIRCH ST	UNK	UNK-LG	UNK	C	SF	SL repair/replace record	N	Field inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	608 BLUFF ST	N	P	UNK	1"	2018 C	Installation record	N	Field inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	608 N MAIN ST	N	UNK-NoL	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2011 Visual Insp at meter	Street Side: No records (may contain lead);
	608 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	609 BIRCH ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead);
	609 HARVEY ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2024 Visual Insp at meter	Street Side: No records (may contain lead);
	609 N MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	609 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	609 WESTON ST	UNK	UNK-LG	UNK	C	SF	SL repair/replace record	N	Other - describe in notes	N		Property Side: No records (may contain lead);
	610 N MAIN ST	N	UNK-NoL	UNK	1994 UNK-LG	SF	Other - describe in notes	N	Field inspection only	Y	2019 Visual Insp at meter	Street Side: No records (may contain lead);
	610 S MAIN ST	UNK	UNK-LG	UNK	C	SF	Other - describe in notes	N	Field inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead);
	610 WESTON ST	UNK	UNK-LG	UNK	C	SF						

Building	702 1ST ST W	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	702 S MAIN ST	UNK	UNK-LG	UNK			DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N		Property side service line does not exist. Street Side: No records (may contain lead); Property Side: Aerial photography shows vacant lot;
Lot 1	703 HARVEY ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	703 HARVEY ST	N	C	UNK		2012	DNE	NONRES	SL repair/replace record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lot 2	703 HARVEY ST	N	C	UNK		2012	DNE	NONRES	SL repair/replace record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	703 N MAIN ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
Lot 1	704 MAPLE ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	704 N MAIN ST	N	UNK-NoL	UNK		1994	C	SF	SL repair/replace record	N	Field Inspection only	Y	2011 Visual Insp at meter	Street Side: No records (may contain lead);
Lot 2	704 N MAIN ST	N	C	UNK	1"	1993	DNE	SF	SL repair/replace record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	704 S MAIN ST	N	UNK-NoL	UNK		2000	UNK-LG	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property Side: No records (may contain lead);
	705 BLUFF ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	705 MAPLE ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
Building 1	705 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2024 Visual Insp at meter	Street Side: No records (may contain lead);
	705 W 3RD ST	UNK	UNK-LG	UNK			UNK-LG	MF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
Building 2	705 W 3RD ST	UNK	UNK-LG	UNK			UNK-LG	MF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	706 N MAIN ST	N	C	UNK	1 1/2"	1993	UNK-LG	MF	SL repair/replace record	N	Other - describe in notes	N		Property Side: No records (may contain lead);
Lot 1	706 N MAIN ST	N	UNK-NoL	UNK	1 1/2"	1994	DNE	SF	SL repair/replace record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	707 BLUFF ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
Lot 2	707 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	708 CEDAR ST	N	UNK-NoL	UNK	1"	2012	C	SF	SL repair/replace record	N	Field Inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	708 W 2ND ST	UNK	UNK-LG	UNK			UNK-NoL	SF	Other - describe in notes	N	Other - describe in notes	N		
	708 W MIDDLE ST	N	C	UNK		2012	C	SF	SL repair/replace record	N	Field Inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
710 W Middle St.	708 W MIDDLE ST	UNK	UNK-LG	UNK			P	NONRES	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	709 N MAIN ST	N	UNK-NoL	UNK	1"	1994	C	MF	SL repair/replace record	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	709 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	709 W MIDDLE ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	710 HARVEY ST	UNK	UNK-LG	UNK			C	MF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	710 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead);
Lot 95	710 VALLEY VIEW CT	N	UNK-NoL	N	1"	2000	C	SF	Installed after lead ban	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	710 W 2ND ST A	UNK	UNK-LG	UNK			P	SF	Other - describe in notes	N	Field Inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead);
	711 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	712 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2015 Visual Insp at meter	Street Side: No records (may contain lead);
	713 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	715 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	715 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	718 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	720 N MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	800 SCHOOL ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	800 W 3RD ST	UNK	UNK-LG	UNK			UNK-NoL	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: Aerial photography shows development after lead ban;
	801 1ST ST W	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	801 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2021 Visual Insp at meter	Street Side: No records (may contain lead);
	801 JOHN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	801 N MAIN ST	UNK	UNK-LG	UNK			C	NONRES	Other - describe in notes	N	Field Inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	801 S MAIN ST	N	UNK-NoL	UNK		2000	UNK-LG	SF	Installed after lead ban	N	Other - describe in notes	N		Property Side: No records (may contain lead);
	803 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2017 Visual Insp at meter	Street Side: No records (may contain lead);
	803 JOHN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	803 S BLUFF ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead);
	803 S MAIN ST	UNK	UNK-LG	UNK			P	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	803 W 1ST ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	804 S MAIN ST	N	UNK-NoL	UNK		2000	UNK-LG	SF	Installed after lead ban	N	Other - describe in notes	N		Property Side: No records (may contain lead);
	804 WATER ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	805 BLUFF ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	805 HARVEY ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2019 Visual Insp at meter	Street Side: No records (may contain lead);
	805 JOHN ST	UNK	UNK-LG	UNK			P	SF	Other - describe in notes	N	Field Inspection only	Y	2015 Visual Insp at meter	Street Side: No records (may contain lead);
	805 S MAIN ST	N	UNK-NoL	UNK		2000	C	SF	Installed after lead ban	N	Field Inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	806 BLUFF ST	UNK	UNK-LG	UNK			C	MF	Other - describe in notes	N	Field Inspection only	Y	2020 Visual Insp at meter	Street Side: No records (may contain lead);
	806 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2018 Visual Insp at meter	Street Side: No records (may contain lead);
	807 BLUFF ST	UNK	UNK-LG	UNK			C UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead);
	808 PRECISION PKWY	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	809 S MAIN ST	N	UNK-NoL	UNK		2000	UNK-LG	SF	Installed after lead ban	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	809 WATER ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Property Side: No records (may contain lead);
	811 S MAIN ST	N	UNK-NoL	UNK		2000	P	SF	Installed after lead ban	N	Field Inspection only	Y	2013 Visual Insp at meter	Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	900 FARNAM DR	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	900 HARVEY ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	901 HARVEY ST	UNK	UNK-LG	UNK			UNK-LG	NONRES	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	904 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2014 Visual Insp at meter	Street Side: No records (may contain lead);
	906 S MAIN ST	UNK	UNK-LG	UNK			G	SF	Other - describe in notes	N	Field Inspection only	Y	2012 Visual Insp at meter	Street Side: No records (may contain lead);
	908 S MAIN ST	UNK	UNK-LG	UNK			C	SF	Other - describe in notes	N	Field Inspection only	Y	2016 Visual Insp at meter	Street Side: No records (may contain lead);
	910 S MAIN ST	UNK	UNK-LG	UNK			UNK-LG	SF	Other - describe in notes	N	Other - describe in notes	N		Street Side: No records (may contain lead); Property Side: No records (may contain lead);
	911 S MAIN ST	N	UNK-NoL	UNK		2000	UNK-LG	SF	Installed after lead ban	N	Other - describe in notes	N		Property Side: No records (may contain lead);
Bayview Cemetery Lot 1	Bayview Cemetery Lot 1	N	UNK-NoL	UNK		1994	DNE	NONRES	SL repair/replace record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bayview Cemetery Lot 2	N	UNK-NoL	UNK		1994	DNE	NONRES	SL repair/replace record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 1	Bluffview Ct Lot 1	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 10	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 11	Bluffview Ct Lot 11	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 12	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 13	Bluffview Ct Lot 13	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 14	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 15	Bluffview Ct Lot 15	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 16	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 17	Bluffview Ct Lot 17	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 2	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 3	Bluffview Ct Lot 3	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 4	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 5	Bluffview Ct Lot 5	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 6	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 7	Bluffview Ct Lot 7	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Bluffview Ct Lot 8	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Bluffview Ct Lot 9	Bluffview Ct Lot 9	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Burch Circle Dr Lot 1	N	C	N	1"	1994	DNE	NONRES	Installation record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Burch Circle Dr Lot 2	Burch Circle Dr Lot 2	N	C	N	1"	1994	DNE	NONRES	Installation record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Empty lot west of 201 Friendship Rd	N	UNK-LG	UNK			DNE	NONRES	Other - describe in notes	N	Other - describe in notes	N		1998 Friendship Rd Watermain Replacement Drawings Indicate partial replacement of street side SL at main Property side service line does not exist
Garage	Garage	N	C	UNK		1994	DNE	NONRES	Installation record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Kudrinsk St Lot 1	N	UNK-LG	UNK	1"	2002	DNE	NONRES	SL repair/replace record	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 71	Lakeview Ct Lot 71	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Lakeview Ct Lot 72	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 73	Lakeview Ct Lot 73	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Lakeview Ct Lot 74	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 75	Lakeview Ct Lot 75	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Lakeview Ct Lot 76	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 77	Lakeview Ct Lot 77	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Lakeview Ct Lot 78	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
Lakeview Ct Lot 79	Lakeview Ct Lot 79	N	UNK-NoL	N	1"	2000	DNE	NONRES	Installed after lead ban	N	Other - describe in notes	N		Property side service line does not exist. Property Side: Aerial photography shows vacant lot;
	Lakeview Ct Lot 80	N	UNK-NoL	N	1"	2000	DNE</							

[illegible]

[illegible]